

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2011 Levee Inspection Results

Reclamation District No. 2092 Dos Rios

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 2092 Dos Rios

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Right	3.76

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	6/2/2011 - 6/2/2011			
DWR Inspector	Pavel Kazi			
Accompanied By	Billy Lyons RD 2092			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River							Right	3.76	06/02/2011 06/02/2011	Pavel Kazi
LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.16	0.16	Earthen Levee	Animal Control	LS	A	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.602125 ° -121.160930 °	37.602125 ° -121.160930 °	31 Y
2	0.16	0.16	Earthen Levee	Animal Control	LS	C	Exterminate rodents and backfill and compact or grout burrows.	37.602125 ° -121.160928 °	37.602125 ° -121.160928 °	2
3	0.19	0.19	Interior Drainage & Piping Systems	Flap Gates	WS	C	Inspector Comments: Flap gate propped open, screw gate appears operational.	37.601999 ° -121.161290 °	37.601999 ° -121.161290 °	966
4	0.19	0.19	Interior Drainage & Piping Systems	Flap Gates	WS	A	Inspector Comments: The flap gate has been replaced recently by the LMA.	37.601999 ° -121.161290 °	37.601999 ° -121.161290 °	32 Y
5	0.21	0.24	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	37.601876 ° -121.161644 °	37.601670 ° -121.162186 °	3
6	0.21	0.24	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	37.601876 ° -121.161640 °	37.601670 ° -121.162190 °	33 Y
7	0.38	0.70	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	37.601304 ° -121.164659 °	37.598233 ° -121.167937 °	4
8	0.48	1.79	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	37.600988 ° -121.166480 °	37.584830 ° -121.163280 °	34 Y
9	0.48	1.79	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	37.600988 ° -121.166475 °	37.584830 ° -121.163281 °	5
10	0.62	0.62	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.599204 ° -121.167144 °	37.599204 ° -121.167144 °	6 Y
11	0.63	0.63	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.598848 ° -121.167379 °	37.598848 ° -121.167379 °	20 Y
12	0.63	2.00	Earthen Levee	Seepage / Sandboils	LS	U	Inspector Comments: Seepage occurred in the area.	37.598848 ° -121.167378 °	37.584319 ° -121.159483 °	21 Y
13	0.77	1.33	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.597291 ° -121.168496 °	37.590568 ° -121.164028 °	968 Y
14	0.86	0.86	Earthen Levee	Erosion / Bank Caving	LS	M	Schedule repair of erosion site prior to the next inspection.	37.595986 ° -121.168249 °	37.595986 ° -121.168249 °	22 Y
15	1.31	1.31	Earthen Levee	Slope Stability	LS	M	Repair slope instability.	37.590667 ° -121.164220 °	37.590667 ° -121.164220 °	23 Y
16	1.34	1.57	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.590479 ° -121.163844 °	37.587758 ° -121.162349 °	7
17	1.47	1.47	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.589061 ° -121.162168 °	37.589061 ° -121.162168 °	24
18	1.47	1.47	Earthen Levee	Slope Stability	LS	M	Repair slope instability.	37.589061 ° -121.162168 °	37.589061 ° -121.162168 °	25 Y

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 San Joaquin River				Right	3.76	06/02/2011 06/02/2011	Pavel Kazi	

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
19	1.55	1.69	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 2009: No major change; sloughing at the lower slope that's created a terraced effect; damage could be caused by wave action during an extended flooding; site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:RD2092U1RM84.6]	37.587130 ° -121.162830 °	37.587130 ° -121.162830 °	1 Y
20	1.59	1.87	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	37.587575 ° -121.162454 °	37.584057 ° -121.162387 °	8 Y
21	1.59	1.62	Earthen Levee	Animal Control	LS	M	Repair the levee slope damaged by livestock and prevent large animal access. Inspector Comments: New land owner at this levee mile.	37.587564 ° -121.162459 °	37.587117 ° -121.162732 °	970 Y
22	1.75	1.75	Earthen Levee	Encroachments	LS	M	Tree or limb	37.585342 ° -121.163382 °	37.585342 ° -121.163382 °	26 Y
23	1.88	1.88	Earthen Levee	Trim / Thin Trees	LS	C	Tree stumps.	37.584019 ° -121.162135 °	37.584019 ° -121.162135 °	9
24	1.94	1.94	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	37.584277 ° -121.161080 °	37.584277 ° -121.161080 °	35 Y
25	1.94	1.94	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	37.584277 ° -121.161080 °	37.584277 ° -121.161080 °	10
26	2.02	2.02	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	37.584355 ° -121.159676 °	37.584355 ° -121.159676 °	27 Y
27	2.06	2.06	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	37.584301 ° -121.159075 °	37.584301 ° -121.159075 °	11
28	2.07	2.07	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.584295 ° -121.158809 °	37.584295 ° -121.158809 °	971 Y
29	2.18	2.18	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	37.583507 ° -121.156982 °	37.583507 ° -121.156982 °	12
30	2.26	2.26	Earthen Levee	Trim / Thin Trees	LS	N	Tree stumps.	37.582830 ° -121.156084 °	37.582830 ° -121.156084 °	13 Y
31	2.41	2.41	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.580851 ° -121.156438 °	37.580851 ° -121.156438 °	28 Y
32	2.43	2.43	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	37.580607 ° -121.156627 °	37.580607 ° -121.156627 °	14
33	2.43	2.43	Earthen Levee	Encroachments	WS	M	Equipment	37.580441 ° -121.156758 °	37.580441 ° -121.156758 °	29 Y
34	2.55	2.55	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	37.578933 ° -121.156977 °	37.578933 ° -121.156977 °	15

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River						Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
35	2.73	2.73	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	37.576336 ° -121.157217 °	37.576336 ° -121.157217 °	30 Y
36	2.81	3.08	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	37.575189 ° -121.156991 °	37.574076 ° -121.152391 °	16
37	2.83	2.83	Earthen Levee	Trim / Thin Trees	WS	A	Thin trees to allow visibility of the ground and room to flood fight.	37.574928 ° -121.156500 °	37.574928 ° -121.156500 °	36 Y
38	2.83	2.83	Earthen Levee	Trim / Thin Trees	WS	C	Trim and thin trees to allow visibility of the ground and room to flood fight.	37.574928 ° -121.156498 °	37.574928 ° -121.156498 °	17
39	2.84	3.09	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Barbed wire fence on landward slope.	37.574973 ° -121.156647 °	37.574001 ° -121.152183 °	972 Y
40	3.40	3.40	Earthen Levee	Animal Control	LS	W	Repair the levee slope damaged by livestock and prevent large animal access.	37.573334 ° -121.147022 °	37.573334 ° -121.147022 °	18
41	3.54	3.70	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	37.573291 ° -121.144391 °	37.573257 ° -121.141446 °	19

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	1
Start Levee Mile	0.16
End Levee Mile	0.16
Location	Land Side
Category	Earthen Levee
Item	Animal Control
<p>The rodent holes have been compacted to new soil. The picture was taken from the crown looking upstream.</p>	
pkazi_s_20110602_695.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.19
End Levee Mile	0.19
Location	Water Side
Category	Interior Drainage & Piping Systems
Item	Flap Gates
<p>The flap gate seems to be fully operational and shows no damage since the gate is new. The picture was taken from the waterside of the levee looking upstream.</p>	
pkazi_s_20110602_696.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.21
End Levee Mile	0.24
Location	Land Side
Category	Earthen Levee
Item	Vegetation
<p>Vegetation complies within the standards on the landside slope of the levee. The picture was taken from the crown looking upstream.</p>	
pkazi_s_20110602_697.jpg	

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	8
Start Levee Mile	0.48
End Levee Mile	1.79
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Vegetation complies with the standards at the waterside slope of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_698.jpg



Levee Mile Report Line	10
Start Levee Mile	0.62
End Levee Mile	0.62
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes were found on the landside of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_699.jpg



Levee Mile Report Line	11
Start Levee Mile	0.63
End Levee Mile	0.63
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes were found on the landside of the levee. The picture was taken from the crown looking towards the landside toe of the levee.

pkazi_s_20110602_700.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	12
Start Levee Mile	0.63
End Levee Mile	2.00
Location	Land Side
Category	Earthen Levee
Item	Seepage / Sandboils

Seepage occurred at the toe of the landside of the levee 2 weeks prior to inspection. The picture was taken from the crown looking upstream.

pkazi_s_20110602_701.jpg



Levee Mile Report Line	13
Start Levee Mile	0.77
End Levee Mile	1.33
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of agricultural ditch at the landward toe looking upstream.

pkazi_s_20110328_480.jpg



Levee Mile Report Line	14
Start Levee Mile	0.86
End Levee Mile	0.86
Location	Land Side
Category	Earthen Levee
Item	Erosion / Bank Caving

Erosion occurred due to rain runoff. The picture was taken from the crown looking toward the landside of the levee.

pkazi_s_20110602_702.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	14
Start Levee Mile	0.86
End Levee Mile	0.86
Location	Land Side
Category	Earthen Levee
Item	Erosion / Bank Caving

Slope instability due to erosion occurred on the landside of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_703.jpg



Levee Mile Report Line	15
Start Levee Mile	1.31
End Levee Mile	1.31
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the landside shoulder of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_704.jpg



Levee Mile Report Line	18
Start Levee Mile	1.47
End Levee Mile	1.47
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

A rodent hole was found on the landside of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_705.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	19
Start Levee Mile	1.55
End Levee Mile	1.69
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: No major change; sloughing at the lower slope that's created a terraced effect; damage could be caused by wave action during an extended flooding; site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:RD2092U1RM84.6]

pkazi_s_20110328_471.JPG



Levee Mile Report Line	19
Start Levee Mile	1.55
End Levee Mile	1.69
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: No major change; sloughing at the lower slope that's created a terraced effect; damage could be caused by wave action during an extended flooding; site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:RD2092U1RM84.6]

pkazi_s_20110328_472.JPG



Levee Mile Report Line	19
Start Levee Mile	1.55
End Levee Mile	1.69
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: No major change; sloughing at the lower slope that's created a terraced effect; damage could be caused by wave action during an extended flooding; site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:RD2092U1RM84.6]

pkazi_s_20110328_473.JPG



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	19
Start Levee Mile	1.55
End Levee Mile	1.69
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: No major change; sloughing at the lower slope that's created a terraced effect; damage could be caused by wave action during an extended flooding; site recommended as local maintenance issue, per CLRO CES Evaluation 2008 Report; previously rated "M" [2009 SiteID:RD2092U1RM84.6]

pkazi_s_20110328_474.JPG



Levee Mile Report Line	20
Start Levee Mile	1.59
End Levee Mile	1.87
Location	Water Side
Category	Earthen Levee
Item	Encroachments

View of an agricultural ditch at the waterward toe of the slope.

pkazi_s_20110328_475.jpg



Levee Mile Report Line	21
Start Levee Mile	1.59
End Levee Mile	1.62
Location	Land Side
Category	Earthen Levee
Item	Animal Control

View of rodent holes in landward slope looking upstream.

pkazi_s_20110328_481.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	21
Start Levee Mile	1.59
End Levee Mile	1.62
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent hole on the landside of the slope seems to be bigger since the last inspection. The picture was taken from the crown looking upstream.

pkazi_s_20110602_706.jpg



Levee Mile Report Line	22
Start Levee Mile	1.75
End Levee Mile	1.75
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Tree limbs were found on the landside of the levee looking upstream.

pkazi_s_20110602_707.jpg



Levee Mile Report Line	24
Start Levee Mile	1.94
End Levee Mile	1.94
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Vegetation complies with the standards on the landside slope of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_708.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	26
Start Levee Mile	2.02
End Levee Mile	2.02
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Crown depression was found due to vehicular traffic. The picture was taken from crown looking downstream.	
pkazi_s_20110602_709.jpg	



Levee Mile Report Line	28
Start Levee Mile	2.07
End Levee Mile	2.07
Location	Land Side
Category	Earthen Levee
Item	Animal Control
View of rodent holes in the landward shoulder looking upstream.	
pkazi_s_20110328_482.jpg	



Levee Mile Report Line	30
Start Levee Mile	2.26
End Levee Mile	2.26
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
View of a stump on the landward slope.	
pkazi_s_20110328_477.jpg	

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	31
Start Levee Mile	2.41
End Levee Mile	2.41
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes were found on the landside slope of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_710.jpg



Levee Mile Report Line	33
Start Levee Mile	2.43
End Levee Mile	2.43
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Pipe was left out by the farmer at the waterside of the levee. The picture was taken from the crown looking downstream.

pkazi_s_20110602_711.jpg



Levee Mile Report Line	35
Start Levee Mile	2.73
End Levee Mile	2.73
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the landside of the levee looking upstream.

pkazi_s_20110602_712.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	06/02/2011 06/02/2011	Pavel Kazi

Levee Mile Report Line	37
Start Levee Mile	2.83
End Levee Mile	2.83
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

No trees were found which obstructed the visibility on the waterside of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20110602_713.jpg



Levee Mile Report Line	39
Start Levee Mile	2.84
End Levee Mile	3.09
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of barbed wire fence along the waterward slope looking upstream.

pkazi_s_20110328_483.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor